

MAGI# 0438982504

UNITED S

STATES DEPARTMENT Washington D.C. 20243

THE

Of

INTERIOR

B-3898

HISTORIC PRESERVATION CERTIFICATION APPLICATION — PART 1

(Pursuant to the Tax Reform Act of 1976)

Instructions: Applicant should read the instructions carefully before completing application. No Certification may be made unless a completed application form been received (P.L 94-455). Use typewriter or print clearly In dark Ink to complete the application form. Il additional space Is needed to complete Part1, use Uje reviside or a separate plain sheet of paper clearly Indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the appropriate User Indicating the owner's name and mailing address.

PART 1 E	VALUATION OF SIGNIFICANC	E	
. NAME OF	^{8Q5} Cathedral Stree	t	
	803-805 Cathedral		
Address of pro	perly. Street;	-	21201
City		Maryland State	
Ony		State; unt Vernon Place (Expanded) Histor	ric District
ame ol histori	ic district in which property is located: ${=}$		
2 DESCRIPTION	OF PHYSICAL APPEARANCE:	Significance Certified June 9,	. 1980
	ons lor map and photograph requirements-	use reverse side It necessary)	
•		four-story building (with attic)	six bays wide. The
		stone on the west (principal) elev	_
		by a pair of windows. At the top	
		d supporting wooden brackets and a	
	OF SIGNIFICANCE:		,
(use reverse s	side II necessary)		
803 Cat	thedral Street contributes	to the significance of the Mount	Vernon Historic
Distric	ct. The District is signi:	ficant as a residential, in-town r	neighborhood con-
taining	g individual, landmark stru	ctures (e.g., Peabody Conservatory	y) linked by (see back)
Date of construct	ion (il known): 1850 ^s	Original site DMoved Date of alterations (if kr	nown): 1890
	,		1950'S
4. NAME AND MA	AILING ADDRESS OF OWNER:		
	803 Cathedral Associate	es - Robert Russell	
Name			
	c/o Investment Counselo	ors of MD, 803 Cathedral Street	
Street———— City	Bältimore	Gtate. ML	Zip Code 21201
City	301-539-3		zip Code
Telephone Nur	mber (during day): Area Code	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
I hereby attest	that the Information I have provided is to the	best oliny knowledge, correct, and thai I am owner of the	property described above
Thereby allest	and the information i have provided is: to the	bost offiny knowledge, correct, and that I am owner of the	property described above.
5. Signature			Q * - 2 _ = (1 , ' j t 3
For oldce use on	lv		
	•	s ol the National Register historic district and 06 contributes D	does not contribute to the character of
the district.			
	appears D does not appear to meet National Rend with the Department of the Interior procedure	egister Criteria for Evaluation (36 CFR 60.6) and O will likely I res (36 CFR 60).	O will not be nominated to the National
		appear to meet National Register Criteria lor Evaluation (36 CF Interior procedures (36 CFR 60). and D appears D does not app	
-	e>fistoric Preservation OHicer		

This property has been evaluated according to the criteria and procedures set lorth by the Department of the Interior (36 CFR 67) and. Il subject to depreciation under section 167 of the Internal Revenue Code of 1954,

O is hereby certified a historic structure.

Odoes not contribute to the character of the historic district and does not merit certification as a historic structure. Reasons given on the attached sheet.

Signature_______!*>»

2. Description of Physical Appearance (continued) B-3898

cornice. The windows (altered by the previous owner) have one over one sash. Those on the second floor are longer than the others indicating the location of the parlor floor. The four ground floor windows have six over six sash. Evidence exists that the sills and lintels were originally brownstone; over the years, many have been painted or replaced with brick (lintels) or stone (sills). Brick panels exist between the windows on the second and third floors. The building is almost square in plan with a four-story small wing projecting from the center of the rear (east) wall.

Many uses of the building since its construction in the 1850's has eliminated much original detail except for a pair of marble mantels and some pieces of the plaster cornice on the second floor (803) and the original balluster above the second floor (803). The c. 1930's entrance has a leaded fan light and side lights.

Since its construction in the 1850's, 803-805 Cathedral has been a school, two single family residences, apartments, offices, and in the 1950's medical offices. The 1930's renovation involved the addition of structural steel to support the upper floors to create a lobby on the first floor. The last renovation involved the installation of numerous partitions to create medical examining., roomsi'. linoleum flooring, dropped ceilings and man-made/ imitation wood paneling.


Asymmetrically placed dormers light the attic.


3. Statement of Significance (continued)

mid to late 19th century row houses. 803 Cathedral Street is typical in size and construction date with the five-bay houses in the southern part of the district (e.g. 8 West Mount Vernon Place, 706 Cathedral Street and 103 and 105 West Monument Street).

803 Cathedral was constructed in the 1850's probably by Nathaniel Holmes Morison (1815-1890). Morison was born in New Hampshire and educated Harvard before coming to Baltimore to found a ladies' academy. Morison also became the first provost of the Peabody Conservatory. Morison's Academy for Young Ladies operated in the property until 1887. The property was divided and sold in 1893 for two residences. In 1937 it was reunited under one owner. At that time the building underwent a major renovation. In the 1950's the building became doctor's offices. The conversion for medical use was common during the 1950's and 1960's in Mount Vernon providing adaptive uses important to the preservation of the neighborhood.

B-3898 803-805 Cathedral Street Block 0516, Lot 015 Baltimore City Baltimore East Quad.





B-3898

PHOTO A

803 Cathedral Street

West Elevation



PHOTO B

East side of 800 block of Cathedral Street

looking north to Read Street

